

The Chain Mail Guy

Authentic Armour and Cool Club Clothing

www.chainmailguy.com

INCHES-MILLIMETER			INCHES-MILLIMETER			INCHES-MILLIMETER		
1/64	.0156	0.397	11/32	.3437	8.731	43/64	.6719	17.066
1/32	.0312	0.794		.3543	9.000	11/16	.6875	17.462
	.0394	1.000	23/64	.3594	9.128	45/64	.7031	17.859
3/64	.0469	1.191	3/8	.3750	9.525		.7087	18.000
1/16	.0625	1.587	25/64	.3906	9.922	23/32	.7187	18.256
5/64	.0781	1.984		.3937	10.000	47/64	.7344	18.653
	.0787	2.000	13/32	.4062	10.319		.7480	19.000
3/32	.0937	2.381	27/64	.4219	10.716	3/4	.7500	19.050
7/64	.1094	2.778		.4331	11.000	49/64	.7656	19.447
	.1181	3.000	7/16	.4375	11.112	25/32	.7812	19.844
1/8	.1250	3.175	29/64	.4531	11.509		.7874	20.000
9/64	.1406	3.572	15/32	.4687	11.906	51/64	.7969	20.241
5/32	.1562	3.969		.4724	12.000	13/16	.8125	20.637
	.1575	4.000	31/64	.4844	12.303		.8268	21.000
11/64	.1719	4.366	1/2	.5000	12.700	53/64	.8281	21.034
3/16	.1875	4.762		.5118	13.000	27/32	.8437	21.431
	.1968	5.000	33/64	.5156	13.097	55/64	.8594	21.828
13/64	.2031	5.159	17/32	.5312	13.494		.8661	22.000
7/32	.2187	5.556	35/64	.5469	13.891	7/8	.8750	22.225
15/64	.2344	5.953		.5512	14.000	57/64	.8906	22.622
	.2362	6.000	9/16	.5625	14.287		.9055	23.000
1/4	.2500	6.350	37/64	.5781	14.684	29/32	.9062	23.019
17/64	.2656	6.747		.5906	15.000	59/64	.9219	23.416
	.2756	7.000	19/32	.5937	15.081	15/16	.9375	23.812
9/32	.2812	7.144	39/64	.6094	15.478		.9449	24.000
19/64	.2969	7.541	5/8	.6250	15.875	61/64	.9531	24.209
5/16	.3125	7.937		.6299	16.000	31/32	.9687	24.606
	.3150	8.000	41/64	.6406	16.272		.9843	25.000
21/64	.3281	8.334	21/32	.6562	16.669	63/64	.9844	25.003
				.6693	17.000		1.0000	25.400